



HEAVY BEAUMS HYDROMETER

FEATURES

- Used to measure the density of liquid.
- The lower density of the liquid, the deeper hydrometer sinks.
- This hydrometer used for heavy liquids, calibrated at 20°C
- Scale range 1.000 to 1.500.
- Made of clear glass

